

CENTERS FOR MEDICARE & MEDICAID SERVICES

454 11/10/12

STATEMENT OF DEFICIENCIES  
AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA  
IDENTIFICATION NUMBER:

44E232

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01

B. WING

(X3) DATE SURVEY  
COMPLETED

09/23/2012

NAME OF PROVIDER OR SUPPLIER

BLED SOE COUNTY NURSING HOME

STREET ADDRESS, CITY, STATE, ZIP CODE  
107 WHEELERTOWN AVENUE  
PIKEVILLE, TN 37367

(X4) ID  
PREFIX  
TAG

SUMMARY STATEMENT OF DEFICIENCIES  
(EACH DEFICIENCY MUST BE PRECEDED BY FULL  
REGULATORY OR LSC IDENTIFYING INFORMATION)

ID  
PREFIX  
TAG

PROVIDER'S PLAN OF CORRECTION  
(EACH CORRECTIVE ACTION SHOULD BE  
CROSS-REFERENCED TO THE APPROPRIATE  
DEFICIENCY)

(X5)  
COMPLETION  
DATE

K 018  
SS=D

NFPA 101 LIFE SAFETY CODE STANDARD

Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1 3/4 inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. 19.3.6.3

Roller latches are prohibited by CMS regulations in all health care facilities.

This STANDARD is not met as evidenced by:  
Based on observations, it was determined the facility failed to maintain the doors protecting the corridors.

The findings included:

On 9/22/12 at 10:30 AM, observation of the resident room 102 entry door revealed the door was sticking to the door frame and required more than fifteen (15 lbf) pound force to open and close.

The finding was acknowledged by the

K 018

K 018

1.) WHAT CORRECTIVE ACTION WILL BE ACCOMPLISHED FOR THOSE RESIDENTS FOUND TO BE AFFECTED BY THE DEFICIENT PRACTICE?

Maintenance department trimmed the door protection from the door in room 102 to allow the door to open without sticking to the door frame. 10/10/12

2.) HOW WILL YOU IDENTIFY OTHER RESIDENTS HAVING THE POTENTIAL TO BE AFFECTED BY THE SAME DEFICIENT PRACTICE?

Maintenance department will check all of the doors of the resident's rooms to ensure no other doors are sticking to the door frame by 11/10/12

11/10/12

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Stephanie Bunch

TITLE

Administrator

(X6) DATE

10/17/12

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES  
AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA  
IDENTIFICATION NUMBER:

44E232

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01

B. WING

(X3) DATE SURVEY  
COMPLETED

09/23/2012

NAME OF PROVIDER OR SUPPLIER

BLEDSOE COUNTY NURSING HOME

STREET ADDRESS, CITY, STATE, ZIP CODE

107 WHEELERTOWN AVENUE

PIKEVILLE, TN 37367

(X4) ID  
PREFIX  
TAG

SUMMARY STATEMENT OF DEFICIENCIES  
(EACH DEFICIENCY MUST BE PRECEDED BY FULL  
REGULATORY OR LSC IDENTIFYING INFORMATION)

ID  
PREFIX  
TAG

PROVIDER'S PLAN OF CORRECTION  
(EACH CORRECTIVE ACTION SHOULD BE  
CROSS-REFERENCED TO THE APPROPRIATE  
DEFICIENCY)

(X5)  
COMPLETION  
DATE

K 018  
SS=D

NFPA 101 LIFE SAFETY CODE STANDARD

Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1 1/4 inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. 19.3.6.3

Roller latches are prohibited by CMS regulations in all health care facilities.

This STANDARD is not met as evidenced by:  
Based on observations, it was determined the facility failed to maintain the doors protecting the corridors.

The findings included:

On 9/22/12 at 10:30 AM, observation of the resident room 102 entry door revealed the door was sticking to the door frame and required more than fifteen (15 lbs) pound force to open and close.

The finding was acknowledged by the

K 018

3.) WHAT MEASURES  
WILL BE PUT INTO  
PLACE OR WHAT  
CHANGES WILL YOU  
MAKE TO ENSURE  
THAT THE DEFICIENT  
PRACTICE DOES NOT  
RECUR?

Maintenance department will check all of the doors of the resident's rooms to ensure no other doors are sticking to the door frame by 11/10/12

4.) HOW THE CORRECTIVE  
ACTION(S) WILL BE  
MONITORED TO ENSURE  
THE DEFICIENT PRACTICE  
WILL NOT RECUR?

Maintenance staff will continue to monitor all resident room doors to ensure all doors open and close properly without sticking.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Stephanie Bunt

TITLE

Administrator

(X6) DATE

10/17/12

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>44E232</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 - MAIN BUILDING 01</b> B. WING _____	(X3) DATE SURVEY COMPLETED  <b>09/23/2012</b>
---	--	---	--

NAME OF PROVIDER OR SUPPLIER  <b>BLEDSOE COUNTY NURSING HOME</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>107 WHEELERTOWN AVENUE PIKEVILLE, TN 37367</b>
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X6) COMPLETION DATE
K 018	Continued From page 1 Administrator and verified by the Maintenance Director during the exit interview on 9/22/12.	K 018		
K 025 SS=E	<b>NFPA 101 LIFE SAFETY CODE STANDARD</b>  Smoke barriers are constructed to provide at least a one half hour fire resistance rating in accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two separate compartments are provided on each floor. Dampers are not required in duct penetrations of smoke barriers in fully ducted heating, ventilating, and air conditioning systems. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4  This STANDARD is not met as evidenced by: Based on observations, it was determined the facility failed to protect the fire and smoke barriers.  The findings included:  On 9/22/12 at 1:00 AM observation within the health information management office revealed a penetration in the corridor side wall.  This finding was acknowledged by the Administrator and verified by the Maintenance Director during the exit interview on 9/22/12.	K 025	<b>K 025</b>  <b>1.) WHAT CORRECTIVE ACTION WILL BE ACCOMPLISHED FOR THOSE RESIDENTS FOUND TO BE AFFECTED BY THE DEFICIENT PRACTICE?</b>  Maintenance Department placed a blank cover over open area on wall in HIM office. 10/3/12  <b>2.) HOW WILL YOU IDENTIFY OTHER RESIDENTS HAVING THE POTENTIAL TO BE AFFECTED BY THE SAME DEFICIENT PRACTICE?</b>  Maintenance department will check all walls in the nursing home for penetrations by 11/10/12	11/10/12
K 050 SS=F	<b>NFPA 101 LIFE SAFETY CODE STANDARD</b>  Fire drills are held at unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware	K 050		

*Continued*

**CENTERS FOR MEDICARE & MEDICAID SERVICES**

STATEMENT OF DEFICIENCIES  
AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA  
IDENTIFICATION NUMBER:

44E232

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01  
B. WING

(X3) DATE SURVEY  
COMPLETED

09/23/2012

NAME OF PROVIDER OR SUPPLIER

BLEDSOE COUNTY NURSING HOME

STREET ADDRESS, CITY, STATE, ZIP CODE  
107 WHEELERTOWN AVENUE  
PIKEVILLE, TN 37367

(X4) ID  
PREFIX  
TAG

SUMMARY STATEMENT OF DEFICIENCIES  
(EACH DEFICIENCY MUST BE PRECEDED BY FULL  
REGULATORY OR LSC IDENTIFYING INFORMATION)

ID  
PREFIX  
TAG

PROVIDER'S PLAN OF CORRECTION  
(EACH CORRECTIVE ACTION SHOULD BE  
CROSS-REFERENCED TO THE APPROPRIATE  
DEFICIENCY)

(X5)  
COMPLETION  
DATE

K 018

Continued From page 1  
Administrator and verified by the Maintenance  
Director during the exit interview on 9/22/12.  
NFPA 101 LIFE SAFETY CODE STANDARD

K 018

K 025  
SS=E

Smoke barriers are constructed to provide at  
least a one half hour fire resistance rating in  
accordance with 8.3. Smoke barriers may  
terminate at an atrium wall. Windows are  
protected by fire-rated glazing or by wired glass  
panels and steel frames. A minimum of two  
separate compartments are provided on each  
floor. Dampers are not required in duct  
penetrations of smoke barriers in fully ducted  
heating, ventilating, and air conditioning systems.  
19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4

K 025

3.) WHAT MEASURES  
WILL BE PUT INTO  
PLACE OR WHAT  
CHANGES WILL YOU  
MAKE TO ENSURE  
THAT THE DEFICIENT  
PRACTICE DOES NOT  
RECUR?

Maintenance department will check  
all walls in the nursing home for  
penetrations by 11/10/12

This STANDARD is not met as evidenced by:  
Based on observations, it was determined the  
facility failed to protect the fire and smoke  
barriers.

The findings included:

On 9/22/12 at 1:00 AM observation within the  
health information management office revealed a  
penetration in the corridor side wall.

This finding was acknowledged by the  
Administrator and verified by the Maintenance  
Director during the exit interview on 9/22/12.  
NFPA 101 LIFE SAFETY CODE STANDARD

K 050

K 050  
SS=F

Fire drills are held at unexpected times under  
varying conditions, at least quarterly on each shift.  
The staff is familiar with procedures and is aware

4.) HOW THE CORRECTIVE  
ACTION(S) WILL BE  
MONITORED TO ENSURE  
THE DEFICIENT PRACTICE  
WILL NOT RECUR?

Maintenance staff will continue to  
monitor for other penetrations  
throughout the facility on a regular  
basis.

**CENTERS FOR MEDICARE & MEDICAID SERVICES**

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>44E232</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 - MAIN BUILDING 01</b> B. WING _____	(X3) DATE SURVEY COMPLETED  <b>09/23/2012</b>
---	--	---	--

NAME OF PROVIDER OR SUPPLIER

**BLEDSOE COUNTY NURSING HOME**

STREET ADDRESS, CITY, STATE, ZIP CODE  
**107 WHEELERTOWN AVENUE  
PIKEVILLE, TN 37367**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 050	<p>Continued From page 2</p> <p>that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9 PM and 6 AM a coded announcement may be used instead of audible alarms. 19.7.1.2</p> <p>This STANDARD is not met as evidenced by: Based on observations during the fire drill, the facility failed to train the staff on fire drill procedures.</p> <p>The findings included:</p> <p>On 9/23/12 at 12:30 PM, observation within the South Hall area during the fire drill revealed there was a food cart obstructing the corridor access.</p> <p>This finding was acknowledged by the Administrator and verified by the Maintenance Director during the exit interview on 9/23/12.</p>	K 050	<p><u><b>K 050</b></u></p> <p><b>1.) WHAT CORRECTIVE ACTION WILL BE ACCOMPLISHED FOR THOSE RESIDENTS FOUND TO BE AFFECTED BY THE DEFICIENT PRACTICE?</b></p> <p>No particular resident was affected.</p> <p>Maintenance Department will conduct extra fire drills on each shift until all employees are re-trained.</p> <p><b>2.) HOW WILL YOU IDENTIFY OTHER RESIDENTS HAVING THE POTENTIAL TO BE AFFECTED BY THE SAME DEFICIENT PRACTICE?</b></p> <p>No resident was affected, however all residents have the potential to be affected.</p>	11/10/12

*Continued*

**CENTERS FOR MEDICARE & MEDICAID SERVICES**

STATEMENT OF DEFICIENCIES  
AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA  
IDENTIFICATION NUMBER:

44E232

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01

B. WING

(X3) DATE SURVEY  
COMPLETED

09/23/2012

NAME OF PROVIDER OR SUPPLIER

BLEDSOE COUNTY NURSING HOME

STREET ADDRESS, CITY, STATE, ZIP CODE

107 WHEELERTOWN AVENUE

PIKEVILLE, TN 37367

(X4) ID  
PREFIX  
TAG

SUMMARY STATEMENT OF DEFICIENCIES  
(EACH DEFICIENCY MUST BE PRECEDED BY FULL  
REGULATORY OR LSC IDENTIFYING INFORMATION)

ID  
PREFIX  
TAG

PROVIDER'S PLAN OF CORRECTION  
(EACH CORRECTIVE ACTION SHOULD BE  
CROSS-REFERENCED TO THE APPROPRIATE  
DEFICIENCY)

(X5)  
COMPLETION  
DATE

K 050

Continued From page 2  
that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9 PM and 8 AM a coded announcement may be used instead of audible alarms. 19.7.1.2

This STANDARD is not met as evidenced by:  
Based on observations during the fire drill, the facility failed to train the staff on fire drill procedures.

The findings included:

On 9/23/12 at 12:30 PM, observation within the South Hall area during the fire drill revealed there was a food cart obstructing the corridor access.

This finding was acknowledged by the Administrator and verified by the Maintenance Director during the exit interview on 9/23/12.

K 050

3.) WHAT MEASURES  
WILL BE PUT INTO  
PLACE OR WHAT  
CHANGES WILL YOU  
MAKE TO ENSURE  
THAT THE DEFICIENT  
PRACTICE DOES NOT  
RECUR?

Extra fire drills have been  
conducted 10/12/12 and 10/15/12

Maintenance Department will  
conduct at least 1 (one) fire drill on  
each shift until all employees are re-  
trained.  
By 11/10/12

Maintenance staff will continue to  
give instructions during the annual  
update/orientations conducted  
monthly regarding proper fire drill  
procedures.

Maintenance staff will double check  
both halls during fire drills to ensure  
the halls are cleared of equipment.

4.) HOW THE CORRECTIVE  
ACTION(S) WILL BE  
MONITORED TO ENSURE  
THE DEFICIENT PRACTICE  
WILL NOT RECUR?

Maintenance staff will double check  
both halls during fire drills to ensure  
the halls are cleared of equipment.